

जवाहरलाल नेहरू पत्तन प्राधिकरण

JAWAHARLAL NEHRU PORT AUTHORITY

ISO 9001 : 2015 ISO 14001 : 2015 ISO 27001 : 2013 ISO 45001 : 2018

पत्तन कार्यालय : प्रशासन भवन, शेवा, नवी मुंबई - 400707. Port Office : Administration Bldg., Sheva, Navi Mumbai - 400 707. मुख्य सतर्कता अधिकारी Chief Vigilance Officer * (022) 2724 4151 ; मुख्य प्रबंधक (प्रशासन) एवं सचिव Chief Manager (Admn.) & Secy - (022) 2724 4021 ; मुख्य प्रबंधक (यातायात) Chief Manager (Traffic) - (022) 2724 4191; मुख्य प्रबंधक (या.एव.वि.अ.) Chief Manager (M&EE) - (022) 2724 4181 ; मुख्य प्रबंधक (वित्त) Chief Manager (Fin) - (022) 2724 4081; मुख्य प्रबंधक (प.यो.वि.) Chief Manager (PP&D) - (022) 2724 4156 उप-संरक्षक Dy. Conservator (022) 2724 4171; हार्बर मास्टर (022) 2724 4173.

Website : www.jnport.gov.in • E-mail : info@jnport.gov.in

JNP/Marine/DC/Nav.Safety/2022/919

16th November, 2022

LOCAL NOTICE TO MARINERS NO. 06/2022

- Sub: 1. Maintenance Dredging of the entire Mumbai Port & JN Port Navigation Channel by Dredging Corporation of India (DCI).
 - 2. Capital Dredging of BMCTPL Phase-II
- 1. The Maintenance Dredging of the entire Mumbai Port and JN Port Navigation Channel from Section A to F for the year 2022-2023 has commenced w.e.f. 04-11-2022. The crafts proposed to be deployed for survey/dredging works are survey Boats ME Queen, TSHD 'Antigoon' WID 'ASL Bulan', and work boat 'MT Arshiya'.
- 2. Capital Dredging of BMCTPL Phase-II berth pocket has commenced from October, 2022 & will continue till March, 2023. The details of crafts which will be involved in capital dredging are TSHD Volvox Olympila, TSHD Volvox Aisa, Bed Levellen Antareja, Survey Boarts Aero Express. Force & work Boar SB8M2. Additionally, a list of crafts are attached.
- 3. All these crafts will be manning VHF Channel 12, 13 & 16. The TSHD's & self propelled habour barges will be dumping the dredged spoil material in Dumping Station (DS-3). The coordinates of which are given below:

	Latitude	Longitude	
1	18°53' 48"N	072°40' 55"E	
2	18°53' 48"N	072°42' 00"E	
3	18°54' 57"N	072°42' 00"E	
4	18°54' 57"N	072°40' 56"E	

All mariners are hereby advised to take note of the above while passing the Dredgers in the channel. The local fishing community is hereby advised to not to lay their nets in the Anchorage areas and Navigation Channel/Maneuvering areas of JN Port (as highlighted in the copy enclosed).

The following Navigation charts will be affected.

2076 (INT 7338) JN Port & Trombay 2015 (INT 7337) Port of Mumbai

2016 (INT 7336) Inner Approach to Mumbai

Deputy Conservator

To

1. Ship Owners/Masters/Agents

- 2. MANSA/CSLA/INSA/ONGC Nhava Base/Gujarat Ambuja Cement
- 3. Dy.Conservator, MbPT
- 4. DG Shipping
- Maharashtra Maritime Board
- 6. Department of Fisheries
- 7. National Hydrographic Office, Dehradun
- 8. Sr.Commandant(CISF) with a request to sensitize the local fishing community.
- 9. Asstt.Manager(Mktg.)

for uploading on JNP Website.

